

Legend

- NO 1,4-Dioxane (14X) DETECTED
- DETECTED 14X < 6.1 ug/L PERFORMANCE STANDARD
- DETECTED 14X > 6.1 ug/L PERFORMANCE STANDARD
- EXTRACTION WELL
- GROUNDWATER MONITORING WELL

J = ESTIMATED VALUE

U = UNDETECTED

Note: Extraction at MW114-WD did not start until 11/17/08

N

0 200 400 800 Feet

1 inch = 400 feet

FIGURE C-5.6
SECTION 31
1,4-DIOXANE RESULTS
FOURTH QUARTER 2009

O&M Status Report - 2nd Half 2009
North End
Lowry Landfill Superfund Site, Colorado

PARSONS

Denver, Colorado

S:\ES\Maj\Proj\LWRYLNFL\QUARTERLY REPORTS\2nd Half 2009\GIS\14Dioxane_Sec31_4Q09_2/10/10.lxh