

FIGURE 4.15
NBBW AREA
WEATHERED DAWSON
POTENTIOMETRIC SURFACE

8 OCTOBER 2010

O&M Status Report - 2nd Half 2010
Lowry Landfill Superfund Site

PARSONS
Denver, Colorado