

S:\ES\Map\proj\WRY\NFI\QUARTERLY REPORTS\2nd Half 2008\GIS\WD_Sec1930_WaterLevels\Q08r_3/4/09.km

Legend

- NO 1,4-Dioxane (14X) DETECTED
- DETECTED 14X < 6.1 ug/L PERFORMANCE STANDARD
- DETECTED 14X > 6.1 ug/L PERFORMANCE STANDARD
- EXTRACTION WELL
- ⊕ Groundwater Monitoring Well
- ⊕ Direct-Push Groundwater Sample Location
- ⊕ Domestic Well Location
- ⊗ Surface Water Sample Location

J = ESTIMATED VALUE
U = UNDETECTED




FIGURE C-5.8
SECTION 19 AND 30
1,4-DIOXANE RESULTS
FOURTH QUARTER 2008
North End
Lowry Landfill Superfund Site, Colorado
PARSONS
Denver, Colorado